


FINE spol. s r.o. Závěrka 12, Praha 6, 169 00		<b>Dynamic probing (DPT)</b>		<b>DPT1</b>
Project: <b>Apartment building "Moonlighting" - Geological survey</b>				
Project ID: AA_0014 - 2019	Annex no.: 123.B	Type of test: <b>DPH</b>		
Location: Horní 128-37/ Svitavy	Type of cone: Fixed / 15 cm <sup>2</sup>		Type of anvil: Loose / 18 kg	
Measured: Joe Fieldman	Coordinate X: 1039757,71	Acc. to standard: EN ISO 22476-2		
Evaluated: Anthony Old	Coordinate Y: 745200,84	Penetration depth interval: 0,10 m		
Date of test: 26.09.2018	Coordinate Z: 208,00 m	Overall depth: 7,60 m		
Scale: one page	GWT: 5,00 m			



**Notes:**

- Sunny/ Partially cloudy/ Calm
- Testing equipment Borrodril
- Raw data not modified
- Equipment checked and in accordance with EN ISO 22476-2, 5.1